ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0642, W0723, W0638, W0648, W0686, W0743, W0696, W

Street Name
4th Crs, NA, 2nd Main Rd, 3rd Main Rd

Significant Landmark
Umesh house Main Road at gangamma temple

Segment No.
11/C-W0642/S105211

Total Length (m)
378.36

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	70.67	77.549049	13.059807	77.549103	13.060444	W0723	SWD
2	227.54	77.549093	13.057676	77.549074	13.059730	I0246	SWD
3	80.15	77.548407	13.058555	77.548410	13.059280	W0735	W0638

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Umesh house main road and cross roads at gangamma gudi gangamma temple in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Y

Sanctioned Estimated Amount (Rs.)
1000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Improvements to Umesh house main road and cross roads at gangamma gudi gangamma temple in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-14-000019

Work Order No.
EE/BTP/KRIDL/WO/364/2014-15

Work Order Date
20/04/2015

Period of Extention
60 DAYS

Defect Liability Period From
28/05/2015

Defect Liability Period To
27/05/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

KRIDL 0.00

Phone No. **E-Mail ID**

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
3		RANGANATH
Date of Inspection	**Remarks**	
09/03/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0642, W0723, W0638, W0648,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	09/03/2017	08/04/2017	COMPLETED
SE	VASU K M	09/03/2017	08/04/2017	COMPLETED
EE	SRINIVAS	09/03/2017	08/04/2017	COMPLETED
AEE	SRINIVASRU	09/03/2017	08/04/2017	COMPLETED
AE	RANGANATH	09/03/2017	08/04/2017	COMPLETED
AE	RANGANATH	09/03/2017	08/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0642, W0723, W0638, W0648,